Exhibit 1

						<u> </u>
12476	CN	3/17/03	Letter (attached to claim form)	Letter from City of Vancouver to Speights & Runyan re: construction date of building	100 Oak Street Hampton, SC	Speights & Runyan
12476	CN	6/06/84	Report	Building Inspection for the Presence and Condition of Friable Asbestos	100 Oak Street Hampton, SC	Speights & Runyan
12476	CN	2/17/89	Report	Hazard Assessment Survey by Pinchin- Harris and Associates	100 Oak Street Hampton, SC	Speights & Runyan
12476	CN	4/05/89	Report		100 Oak Street Hampton, SC	Speights & Runyan
12476	CN	11/17/89	Report	Monitoring of Asbestos Abatement - Projection Room	100 Oak Street Hampton, SC	Speights & Runyan
12476	CN	11/00/89	Report	Occupational Health Hazard Assessment of Asbestos prepared by Monenco	100 Oak Street Hampton, SC	Speights & Runyan
12476	CN	5/29/91	Report	Asbestos Hazard Re-Survey	100 Oak Street Hampton, SC	Speights & Runyan
12476	CN	6/11/91	Report	Asbestos Analyses Results	100 Oak Street Hampton, SC	Speights & Runyan
12476	CN	6/23/92	Chart	Asbestos Hazard Assessment Record	100 Oak Street Hampton, SC	Speights & Runyan
12476	CN	7/13/92	Letter/Report	Letter from ACM Services to City of Vancouver re: Queen of Elizabeth Theatre Restaurant Asbestos Removal Project with attached inspection reports and air sampling results	100 Oak Street Hampton, SC	Speights & Runyan
12476	CN	6/22/95	Report	Air Monitoring Results - Queen Elizabeth Theatre	100 Oak Street Hampton, SC	Speights & Runyan
12476	CN	Undated	Report	Hazard Assessments Survey conducted by Pinchin Harris Holland	100 Oak Street Hampton, SC	Speights & Runyan
12476	CN	Undated	Specs	Asbestos Removal Specifications	100 Oak Street Hampton, SC	Speights & Runyan
12476	CN	Undated	Report	Tender Documents	100 Oak Street Hampton, SC	Speights & Runyan
12476	CN	Undated	Report	Tender Documents with attached drawings	100 Oak Street Hampton, SC	Speights & Runyan